# CLUTCH STAYOUT AT HIGH RPM—BUILT ON OR **BEFORE 4/25/2010**

TSB 10-19-4

#### FORD:

2011 Mustang

### **ISSUE**

Some 2011 Mustangs built on or before 4/25/2010, with a manual transmission and low mileage, typically 10,000 miles or less (16,093 Km), may exhibit a clutch pedal Stayout condition at very high engine RPM. This condition will generate a concern of the clutch pedal remaining on the floor during high engine RPM shifts. When engine RPM drops, clutch pedal operation returns to normal, but the re-engagement may be abrupt.

## **ACTION**

Follow the Service Procedure steps to correct the condition.

#### **SERVICE PROCEDURE**

The clutch pedal Stayout is a condition where at high engine RPM, centrifugal forces on the clutch system can reduce the force with which the clutch diaphragm fingers push against the release bearing. This can result in the clutch pedal staying on the floor until engine RPM decreases and the diaphragm return force increases.

1. Replace the Brake Pedal and Bracket assembly. Refer to Workshop Manual, Section 206-06.

PART NUMBER	PART NAME
BR3Z-2455-M	Brake Pedal And Bracket (Black-3.7L/GT 5.0L w/Brembo Brakes)
BR3Z-2455-P	Brake Pedal And Bracket (Metallic-3.7L/GT 5.0L w/Brembo Brakes)
BR3Z-2455-R	Brake Pedal And Bracket (Black-GT 5.0L Standard Brakes)
BR3Z-2455-T	Brake Pedal And Bracket (Metallic-GT 5.0L Standard Brakes)

WARRANTY STATUS: Eligible Under Provisions Of

New Vehicle Limited Warranty Coverage **IMPORTANT: Warranty** coverage limits/policies are not altered by a TSB. Warranty coverage limits are determined by the identified causal part.

OPERATION **DESCRIPTION** TIME 0.8 Hr.

101904A 2011 Mustang MT82

Transmission: Replace The Brake Pedal And Bracket Assembly (Do Not Use With Any Other Labor

Operations)

**DEALER CODING** 

CONDITION BASIC PART NO. CODE 2455 01

NOTE: The information in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford, Lincoln, or Mercury dealership to determine whether the Bulletin applies to your vehicle. Warranty Policy and Extended Service Plan documentation determine Warranty and/or Extended Service Plan coverage unless stated otherwise in the TSB article. The information in this Technical Service Bulletin (TSB) was current at the time of printing. Ford Motor Company reserves the right to supercede this information with updates. The most recent information is available through Ford Motor Company's on-line technical resources.