



Drivers Side Front

No noticeable rotor surface difference.



Passenger Side Front

Notice the ring at the top of the rotor?

What's causing it and could it be related to the intermittent vibration in the car and steering wheel. No noticeable vibration in the brake pedal when stopping...