

**5.0L AND 2.3L ECOBOOST WITH PERFORMANCE PACKAGE FRONT  
BRAKE NOISE - BUILT ON OR BEFORE 2/11/2015****TSB 15-0030****FORD:**

2015 Mustang

**ISSUE**

Some 2015 Mustang vehicles equipped with 5.0L or 2.3L EcoBoost with performance package built on or before 2/11/2015 may exhibit a front brake squeal condition. These vehicles are equipped with four (4) piston front brake calipers.

**ACTION**

Follow the Service Procedure steps to correct the condition.

**SERVICE PROCEDURE**

Replace both front brake discs and pads. Refer to Workshop Manual (WSM), Section 206-03.

PART NUMBER	PART NAME
GR3Z-1125-E	Rotor Assembly - Brake
FR3Z-2001-A	Caliper Brake Pads

OPERATION	DESCRIPTION	TIME
150030A	2015 Mustang: Replace Both Front Brake Pads And Rotors Equipped With Four (4) Piston Front Brake Calipers (Not To Be Used With Any Other Operation)	0.7 Hr.

**WARRANTY STATUS:**

Eligible Under Provisions Of New Vehicle Limited Warranty Coverage

Warranty/ESP coverage limits/policies/prior approvals are not altered by a TSB. Warranty/ESP coverage limits are determined by the identified causal part and verified using the OASIS part coverage tool.

**DEALER CODING**

BASIC PART NO.	CONDITION CODE
1125	42

NOTE: The information contained in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford, Lincoln, or Mercury dealership to determine whether the bulletin applies to your vehicle. Warranty Policy and Extended Service Plan documentation determine Warranty and/or Extended Service Plan coverage unless stated otherwise in the TSB article. The information in this Technical Service Bulletin (TSB) was current at the time of printing. Ford Motor Company reserves the right to supersede this information with updates. The most recent information is available through Ford Motor Company's on-line technical resources.